
USE SERVO WRITER TO WRITE SERVO TRACKS INCLUDING A TRACK ZERO
21
MOUNT DISK ON A HUB AND SPIN
22
MEASURE DISTANCE TO SELECTED POINTS ON TRACK ZERO USING KERR EFFECT MICROSCOPY
23
CALCULATE AVERAGE DISTANCE FROM THE PLURALITY OF MEASUREMENTS
24
ADJUST SERVO WRITER USING MEASURED POSITION OF TRACK ZERO
25

Figure 1